

# Oil Field Environmental Incident Summary

**Incident:** 20160808095650

**Date/Time of Notice:** 08/08/2016 09:56

**Responsible Party:** HESS CORPORATION

**Well Operator:** HESS CORPORATION

**Well Name:** RAMBERG TRUCK FACILITY

**Field Name:** BEAVER LODGE

**Well File #:**

**Date Incident:** 8/6/2016

**Time Incident:** 18:03

**Facility ID Number:** 700031-01

**County:** WILLIAMS

**Twp:** 156

**Rng:** 95

**Sec:** 32

**Qtr:** SW SW

**Location Description:**

**Submitted By:** Alberto Yates

**Received By:**

**Contact Person:** Troy Brunsell  
3015 16TH ST SW STE 20  
MINOT, ND 58701

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 2275 Feet

**Distance Nearest Water Well:** 2275 Feet

**Type of Incident:** Equipment Failure

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	1.2	Barrels			1.2	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

1.2 bbl. Crude Oil Spill

**Inspected:**

**Written Report Received:** 9/6/2016

**Clean Up Concluded:** 8/27/2016

**Risk Evaluation:**

There is no immediate risk to report at this time. NO OFFSITE IMPACTS

**Areal Extent:**

The spill area is 30'X25'

**Potential Environmental Impacts:**

There are no potential environmental impacts to report at this time. All impacts REMAINED ON SITE. No Sensitive areas were impacted due to the incident.

**Action Taken or Planned:**

Truck pump was ESD and Arrangements for proper removal and disposal affected material have been made.

**Wastes Disposal Location:** The recovered waste will be taken to an approved waste disposal facility.

**Agencies Involved:****Updates**

---

**Date:** 8/8/2016      **Status:** Reviewed - Assigned to Other Agency      **Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release remained on location according to the report. NDIC retains oversight.